


















A1  x32	A2  x32	B5  10x50 x1	C1  8x35 x40	D1  x4
E1  x4	G  1,5x26 x40	H4  x5	I  x1	N2  x6
P1  x8	Q  x2	R1  3x13 x12	R19  6,0x13 x18	R23  6,3x13 x8
R24  7x50 x12	R32  4x27 x10	R102  3,5x16 x10	S5  x20	U  x1
Z3  350 x3				





№	a*b*c	x	№→...
1	445x751x16	2	1/3
2	756x380x16	2	1/3
3	756x380x16	1	1/3
4	756x380x16	1	1/3
5	1550x400x22	1	2/3
6	1550x400x22	1	2/3
8	517x379x16	2	2/3
9	756x100x16	2	1/3
10	1545x397x2,5	2	2/3
11	350x180x16	3	3/3
12	393x180x16	3	3/3
13	350x180x16	3	3/3
14	415x350x2,5	3	2/3
15	445x249x16	3	3/3
			



1




2




3

A2  x12	C1  8x35 x12	P1  x4
---	---	--




4


A1  x4	C1  8x35 x8
---	--




5




6








7





8





9




10_{x3}



11_{x3}






12_{x3}





13

x3





14

x3



15



16

B5
10x50 x1

Q
x2

R102
3,5x16 x2

S5
x8

U
x1

