




# Bunk Bed


## Installation Option I






## Installation Option II














**GAUTION :** When tightening the screws , tighten sequentially .  
Do not tighten any screws fully and then towards the next one .  
When every part is OK , then tighten all the screws





|                                                                                     |      |                                                                                          |                                                                                           |                                                                                                                                                                                                                                                                               |       |                                                                                     |       |                                                                                       |       |                                                                                       |       |
|-------------------------------------------------------------------------------------|------|------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|-------------------------------------------------------------------------------------|-------|---------------------------------------------------------------------------------------|-------|---------------------------------------------------------------------------------------|-------|
| A                                                                                   | x6+1 | B                                                                                        | x32+2                                                                                     | C                                                                                                                                                                                                                                                                             | x5+1  | D                                                                                   | x33+2 | E                                                                                     | x11+1 | F                                                                                     | x15+1 |
|  |      |       |                                                                                           |                                                                                                                                                                                            |       |  |       |  |       |  |       |
| M5x38                                                                               |      | M6x35                                                                                    |                                                                                           |                                                                                                                                                                                                                                                                               |       | M6x17                                                                               |       | M6x50                                                                                 |       | M6x55                                                                                 |       |
| G                                                                                   | x2   | H                                                                                        | x4                                                                                        | I                                                                                                                                                                                                                                                                             | x4    | J                                                                                   | x2    | K                                                                                     | x1    | L                                                                                     | x6+1  |
|  |      | <br>H | <br>H1 |                                                                                                                                                                                            |       |  |       |  |       |  |       |
| M4x10                                                                               |      |                                                                                          |                                                                                           | M6x25                                                                                                                                                                                                                                                                         |       | M4                                                                                  |       |                                                                                       |       | M6x10                                                                                 |       |
| M                                                                                   | x2   | N                                                                                        | x2                                                                                        | O                                                                                                                                                                                                                                                                             | x20+1 | P                                                                                   | x32+2 | Q                                                                                     | x2    | R                                                                                     | x1    |
|  |      |       |                                                                                           |                                                                                                                                                                                            |       |  |       |  |       |  |       |
| M6x70                                                                               |      |                                                                                          |                                                                                           |                                                                                                                                                                                                                                                                               |       |                                                                                     |       |                                                                                       |       |                                                                                       |       |
| S                                                                                   | x4   | T                                                                                        | x8                                                                                        | U                                                                                                                                                                                                                                                                             | x1    | V                                                                                   | x4    | X                                                                                     | x4    |                                                                                       |       |
|  |      |       |                                                                                           | <br>M3<br><br>M4<br> |       |  |       |  |       |                                                                                       |       |
|                                                                                     |      |                                                                                          |                                                                                           |                                                                                                                                                                                                                                                                               |       | M6x15                                                                               |       | M6x20                                                                                 |       |                                                                                       |       |




|                                                                                                           |                                                                                                            |                                                                                                              |
|-----------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------|
| <p>(19)</p>  <p>X1</p>     | <p>(20)</p>  <p>X1</p>     | <p>(21)</p>  <p>X3</p>    |
| <p>(22)</p>  <p>X2</p>   | <p>(23)</p>  <p>X1</p>    | <p>(24)</p>  <p>X4</p>    |
| <p>(25)</p>  <p>X4</p>   | <p>(26)</p>  <p>X4</p>   | <p>(27)</p>  <p>X2</p>   |
| <p>(28)</p>  <p>X9</p>  | <p>(29)</p>  <p>X1</p> | <p>(30)</p>  <p>X16</p> |
| <p>(31)</p>  <p>X4</p> | <p>(32)</p>  <p>X1</p>  |                                                                                                              |

Step 1



|                                                                                      |    |
|--------------------------------------------------------------------------------------|----|
| A                                                                                    | X4 |
|  |    |
| M5x38                                                                                |    |

Step 2




|                                                                                       |    |
|---------------------------------------------------------------------------------------|----|
| H                                                                                     | X4 |
|  |    |
| H                                                                                     | H1 |
|  |    |

## Step 3


It can be installed upside down

Be careful not to overtighten the screws.






## Step 4

It can be installed upside down




Step 5



|                                                                                      |    |
|--------------------------------------------------------------------------------------|----|
| J                                                                                    | X2 |
|   |    |
| M4                                                                                   |    |
| K                                                                                    | X1 |
|   |    |
| G                                                                                    |    |
|   |    |
| M4x10                                                                                |    |
| D                                                                                    | X2 |
|  |    |
| M6x17                                                                                |    |
| L                                                                                    | X2 |
|  |    |
| M6x15                                                                                |    |


Step 6



|                                                                                       |    |
|---------------------------------------------------------------------------------------|----|
| B                                                                                     | X2 |
|  |    |
| M6x35                                                                                 |    |

Step 7



⚠ Be careful not to overtighten the screws.



|                                                                                      |    |
|--------------------------------------------------------------------------------------|----|
| F                                                                                    | X8 |
|  |    |
| M6x55                                                                                |    |

Step 8


⚠ Pay attention to the orientation of square holes




|                                                                                       |    |
|---------------------------------------------------------------------------------------|----|
| B                                                                                     | X4 |
|  |    |
| M6x35                                                                                 |    |

Step 9

Use a tool to push the iron sheet away and clamp it into the square hole




Step 10




|                                                                                       |    |
|---------------------------------------------------------------------------------------|----|
| X                                                                                     | X4 |
|  |    |
| M6x20                                                                                 |    |


Step 11




|                                                                                      |    |
|--------------------------------------------------------------------------------------|----|
| L                                                                                    | X4 |
|  |    |
| M6x10                                                                                |    |

Step 12




|                                                                                       |    |
|---------------------------------------------------------------------------------------|----|
| V                                                                                     | X1 |
|  |    |
| M6x15                                                                                 |    |
| I                                                                                     | X2 |
|  |    |
| M6x25                                                                                 |    |
| A                                                                                     | X2 |
|  |    |
| M5x38                                                                                 |    |

Step 13




Step 14





|                                                                                       |    |
|---------------------------------------------------------------------------------------|----|
| B                                                                                     | X2 |
|  |    |
| M6x35                                                                                 |    |

# Installation Option I






With the basic components of Step1-step14,  
the following installation method is the first.

Step 15-1



|       |    |
|-------|----|
| N     | X2 |
|       |    |
| C     | X3 |
|       |    |
| D     | X3 |
|       |    |
| M6x17 |    |
| E     | X3 |
|       |    |
| M6x50 |    |


Step 16-1



|       |    |
|-------|----|
| F     | X1 |
|       |    |
| M6x55 |    |
| D     | X2 |
|       |    |
| M6x17 |    |
| C     | X2 |
| E     | X2 |
|       |    |
|       |    |
| M6x50 |    |


Step 17-1

Be careful not to overtighten the screws.





|                                                                                      |    |
|--------------------------------------------------------------------------------------|----|
| D                                                                                    | X4 |
|   |    |
| M6x17                                                                                |    |
| E                                                                                    | X4 |
|  |    |
| M6x50                                                                                |    |

Step 18-1



|                                                                                       |    |
|---------------------------------------------------------------------------------------|----|
| D                                                                                     | X4 |
|  |    |
| M6x17                                                                                 |    |
| B                                                                                     | X4 |
|  |    |
| M6x35                                                                                 |    |


Step 19-1



|                                                                                      |    |
|--------------------------------------------------------------------------------------|----|
| D                                                                                    | X8 |
|   |    |
| M6x17                                                                                |    |
| B                                                                                    | X8 |
|  |    |
| M6x35                                                                                |    |

Step 20-1

Be careful not to overtighten the screws.




|                                                                                       |    |
|---------------------------------------------------------------------------------------|----|
| M                                                                                     | X1 |
|  |    |
| M6x70                                                                                 |    |
| F                                                                                     | X2 |
|  |    |
| M6x55                                                                                 |    |
| B                                                                                     | X3 |
|  |    |
| M6x35                                                                                 |    |

## Step 21-1

⚠ avoid the screw head  
when inserting the hole plate


⚠ Pay attention to the  
orientation of part 23



| E                                                                                  | X2 | V                                                                                   | X3 | D                                                                                    | X6 | B                                                                                    | X1 |
|------------------------------------------------------------------------------------|----|-------------------------------------------------------------------------------------|----|--------------------------------------------------------------------------------------|----|--------------------------------------------------------------------------------------|----|
|  |    |  |    |  |    |  |    |
| M6x50                                                                              |    | M6x15                                                                               |    | M6x17                                                                                |    | M6x35                                                                                |    |


## Step 22-1

TIGHT ALL SCREWS 100%




| I                                                                                     | X2 |
|---------------------------------------------------------------------------------------|----|
|  |    |
| M6x25                                                                                 |    |
| F                                                                                     | X2 |
|  |    |
| M6x55                                                                                 |    |

## Step 23-1





## Step 24-1



Step 25-1



The plastic buckle needs to be pushed into the card slot



|   |     |
|---|-----|
| P | X16 |
|   |     |
| O | X10 |
|   |     |



Step 26-1

Clamp the square hole into the convex bloc





## Step 27-1

Clamp the square hole  
into the convex bloc



## Step 28-1



The plastic buckle needs to  
be pushed into the card slot



|   |     |
|---|-----|
| P | X16 |
|   |     |
| O | X10 |
|   |     |


## Step 29-1

S hook hangs into the hole of the hole plate according to your needs




|   |    |
|---|----|
| T | x8 |
|   |    |


## Step 30-1



Be careful to tear off the paper on the back of the light strip, Then press it firmly with your hand




Wall




|   |    |
|---|----|
| S | x4 |
|   |    |
| Q | x2 |
|   |    |
| R | x1 |
|   |    |

## Installation Option II




With the basic components of Step1-step14, the following installation method is the first.

## Step 15-2




## Step 16-2




Step 17-2

⚠ Be careful not to overtighten the screws.



|                                                                                      |    |                                                                                      |    |
|--------------------------------------------------------------------------------------|----|--------------------------------------------------------------------------------------|----|
| D                                                                                    | X4 | E                                                                                    | X4 |
|  |    |  |    |
| M6x17                                                                                |    | M6x50                                                                                |    |


Step 18-2



|                                                                                       |    |
|---------------------------------------------------------------------------------------|----|
| D                                                                                     | X4 |
|  |    |
| M6x17                                                                                 |    |
| B                                                                                     | X4 |
|  |    |
| M6x35                                                                                 |    |

Step 19-2


⚠ Be careful not to overtighten the screws.



⚠ Pay attention to the orientation of the holes

|                                                                                      |    |
|--------------------------------------------------------------------------------------|----|
| D                                                                                    | X8 |
|   |    |
| M6x17                                                                                |    |
| B                                                                                    | X8 |
|  |    |
| M6x35                                                                                |    |

Step 20-2



|                                                                                       |    |                                                                                       |    |
|---------------------------------------------------------------------------------------|----|---------------------------------------------------------------------------------------|----|
| F                                                                                     | X2 | E                                                                                     | X2 |
|  |    |  |    |
| M6x55                                                                                 |    | M6x50                                                                                 |    |



## Step 21-2



Pay attention to the orientation of part 23

TIGHT ALL SCREWS 100%



At the back



| V                                                                                  | X3 | I                                                                                  | X2 | D                                                                                    | X6 | B                                                                                    | X3 |
|------------------------------------------------------------------------------------|----|------------------------------------------------------------------------------------|----|--------------------------------------------------------------------------------------|----|--------------------------------------------------------------------------------------|----|
|  |    |  |    |  |    |  |    |
| M6x15                                                                              |    | M6x25                                                                              |    | M6x17                                                                                |    | M6x35                                                                                |    |



## Step 22-2

Clamp the square hole into the convex bloc





## Step 23-2

Clamp the square hole  
into the convex bloc



## Step 24-2



The plastic buckle needs to  
be pushed into the card slot



|   |     |
|---|-----|
| P | X16 |
|   |     |
| O | X10 |
|   |     |



## Step 25-2

Clamp the square hole  
into the convex bloc




## Step 26-2

Clamp the square hole  
into the convex bloc






Step 27-2



Step 28-2



The plastic buckle needs to be pushed into the card slot



|   |     |
|---|-----|
| P | X16 |
|   |     |
| O | X10 |
|   |     |




## Step 29-2

S hook hangs into the hole of the hole plate according to your needs




|                                                                                      |    |
|--------------------------------------------------------------------------------------|----|
| T                                                                                    | X8 |
|  |    |

## Step 30-2



The slight strip can be placed **under the laminate** according to your own needs



|                                                                                       |    |
|---------------------------------------------------------------------------------------|----|
| Q                                                                                     | X2 |
|  |    |

|                                                                                       |    |                                                                                       |    |
|---------------------------------------------------------------------------------------|----|---------------------------------------------------------------------------------------|----|
| S                                                                                     | x4 | R                                                                                     | x1 |
|  |    |  |    |