

Computer Desk

User Manual



AJ-DJ505372


⚠ Please read this instruction manual carefully before using the product

Installation takes  x 2~4hour

Package Contents

Plates and iron components	Assembly tool kit	Instruction manual


⚠ Precautions




1.Avoid extended periods of direct sunlight exposure.



2.Stay away from fire.




3.Keep away from sharp objects.




4.Keep infants and children away from assembly parts to avoid choking and suffocation.




5.Keep away from corrosive substances.




6. Pay attention to avoid over-tightening fasteners, as they may cause cracking within the board.



7.Prevent objects from being damaged by immersion in water.




8.Prevent object collision and damage.




9.Be careful to avoid collisions.


⚠ Installation of Cams and Pins

Be sure to use the proper screws to avoid damaging the parts





Wrong screws can cause the plank to crack





The right screw is the right size

⚠ Matters needing attention

1. When installing the screws in the installation step, the screws do not need to be tightened.

2. After this installation step is confirmed and the holes are aligned, then tighten all the screws.





3. If the screws are tightened during the installation process, it will cause problems such as misalignment of the screw holes and misalignment of the board in subsequent installations

Disassembly Diagram

BOX A

1 x1 8 x1 9 x1 10 x1 12 x1 13 x1 21 x1 22 x1

23 x1 26 x2 32 x2 35 x2 36 x3 37 x1 40 x1

ACCESSORY BOX

41 x3 42 x2 A x40 B x8 D x14 E x2 F x18 G x29

H x12 I x72 J x72 K x1 L x47 M x2 N x1 O x5

P x20 Q x9 R x9 S x5 T x1 U x1 V x1 W x3

BOX B


2 x1 3 x1 4 x1 5 x1 6 x1 7 x1 11 x1 14 x1

15 x2 16 x2 17 x1 18 x1 19 x1 20 x1 24 x2 25 x1

27 x2 28 x1 29 x1 30 x1 31 x1 33 x2 34 x2 38 x1


39 x1

Disassembly Diagram




Package Contents


01




02




03




04




05




06




07




08




09




10




11




12




13



14




15 x2




Package Contents


16 x2




17




18




19




20




21




22




23




24 x2




25




26 x2




27 x2




28



29




30




Package Contents


31




32 x2




33 x2




34 x2




35 x2




36 x3




37




38




39




40

























41 x3




42 x2




Tool sheet

A x36+4  ST5x40MM	**B** x7+1  M6x10MM	**D** x12+2  M6x38MM	**E** x1+1  M6x48MM
F x16+2  ST4x14MM	**G** x26+3  ST4x12MM	**H** x10+2  M4x12MM	**I** x66+6 
J x66+6 	**K** x1 	**L** x42+5  φ6X30MM	**M** x2 
N x1 	**O** x5 	**P** x18+2 	**Q** x8+1 
R x8+1  Ø5MM	**S** x4+1 	**T** x1  3# 3# 4#	**U** x1 
V x1 	**W** x2+1  ST4x16MM		

Tool sheet






friendly reminder


To avoid errors and confusion during the installation of accessories, use the type and quantity of hardware accessories according to the installation procedure described in the instructions. First, unroll the accessories bag and lay out the hardware accessories, cut holes in the side, and take out the hardware accessories


Assembly Instruction

I x4



1







Pay attention to the positions of the holes indicated by the arrow

Installation instructions for eccentric rod


I




J




01




02



03




04




Assembly Instruction

2

A x2



ST5X40MM




3

J x4




Pay attention to the length from the hole indicated by the arrow to both ends




Assembly Instruction

4




L x6




Φ6X30MM

5




Pay attention to the positions of
the holes indicated by the arrow

A x2



ST5X40MM

L x2




Φ6X30MM


Assembly Instruction

6

Pay attention to the positions of the holes indicated by the arrow




A x6




ST5X40MM


Pay attention to the position of this slot



7




A x1



ST5X40MM


I x12




Assembly Instruction

8

I x4



Pay attention to the positions of
the holes indicated by the arrow




X2

9

J x4




L x4



Φ6X30MM


Pay attention to the positions of
the holes indicated by the arrow




Assembly Instruction

10


J x12







11

P x10









Assembly Instruction

12




L x8




Φ6X30MM

13

The magnetic head can be adjusted front and back




F x4





ST4X14MM

I x8



Mx2






Pay attention to the direction of magnetic poles


Assembly Instruction

14


Pay attention to the position of
the magnetic attraction device



J x8




15



Pay attention to the positions of
the holes indicated by the arrow


Pay attention to the position of
the slot indicated by the arrow

A x2



ST5X40MM

L x2




Φ6X30MM


Assembly Instruction


16


Pay attention to the positions of
the holes indicated by the arrow



I x11








17

J x3







Pay attention to aligning
the slots

Assembly Instruction


18



Gx6




ST4X12MM




Pay attention to the
position of the track wheel


19



Gx6



ST4X12MM




Pay attention to the
position of the track wheel

Assembly Instruction

20

J x4




Pay attention to the positions of
the holes indicated by the arrow

21


J x4



L x4




Φ6X30MM




Pay attention to slot
symmetry

Two people collaborate to prevent
damaging the boards




Assembly Instruction

22




L x6




Φ6X30MM


23



Pay attention to the positions of the holes indicated by the arrow




Ax7




ST5X40MM


Pay attention to the position of this slot




Assembly Instruction

24






Pay attention to the positions of
the holes indicated by the arrow




I x12



25


Pay attention to the positions of
the holes indicated by the arrow



J x4



L x4





Φ6X30MM

Assembly Instruction

26


Jx8








27

Px8










Assembly Instruction


28

Dx6



M6X38MM


Pay attention to the position of the hole indicated by the arrow



Assembly Instruction


29

A x4




ST5X40MM


L x4




Φ6X30MM


Tighten A screws by 70%










Note that the holes indicated by the arrow are located on the upper side




Two people collaborate to avoid tipping over


Assembly Instruction

30


B x1	D x3
 M6X10MM	 M6X38MM
	E x1  M6X48MM


Tighten B、 D and E screws by 70%





Note that the holes indicated by the arrow are located on the upper side






Be careful during installation and do not damage the board

Assembly Instruction


31

I x3




32

L x2



Φ6X30MM


J x3



Assembly Instruction


33

B x6




M6X10MM


D x3




M6X38MM


After installing the board 2 and 3, tighten A、B、D and E screws in step 29 and 30 by 99%





Pay attention to the positions of the holes indicated by the arrow









Pay attention to using the correct screws to fix and avoid damaging the wooden board

Assembly Instruction

34

R x8	V x1	W x2
		
Ø5MM		ST4X16MM


35



Note that board 6 needs to be placed vertically in the cabinet

Assembly Instruction


36




Gx2

ST4X12MM


K x1




Nx1



37




F x8



ST4X14MM


Qx8




Assembly Instruction


38

A x12




ST5X40MM






Assembly Instruction


39






X2


40






X2

I x12



Assembly Instruction

41





X2

J x12




42






X2

H x6




M4x12MM

O x3




Assembly Instruction


43




Gx12




ST4X12MM



X2




44




Assembly Instruction

45




H x4




M4x12MM


O x2



46




F x4




ST4X14MM

S x4




M x2




Assembly Instruction

47





Pay attention to distinguishing
the left and right door panels



The door is not aligned when installed,
and adjusting the door stop can ensure that
the upper part of the door can be aligned flush

The magnetic head can be adjusted front and back






The door panel is flat.

Customer Service



3-years Warranty

We guarantee your product is free from defects in product materia and workmanship for three(3) years starting from the date of purchase during normal use of household conditions.If your appliance fails to operate properly within our warranty period,We will send the corresponding accessories,Replacement is free and all shipping costs are covered



Quick Response within 24 Hours

If you are still unable to resolve the issue, please contact us through the Amazon order page for customer support. Whether the product has been installed or not, our customer support team will respond within 24 hours and assist you promptly.

Problems You May Encounter

Part	Problem	Solution
Cloth drawers	Why use cloth drawers	1. Reducing tree extraction is more environmentally friendly 2. More convenient to use and assemble 3. Reduced the thickness of the side panel, resulting in a larger actual storage space
Whole Produc	Parts are missing, defective or having wrong parts in package	You can contact us and we will get back to you within 24 hours
	Having issue(s) while reading the instruction or completing the assembly	Feel free to contact us and we will get back to you within 24 hours
	Encountering non-human caused damage during usage	If the product is damaged due to non-human causes, please keep the product and send us photos of it. We will ascertain the cause of the product damage within 48 hours and provide you with a satisfactory solution
Table Surface	Board surface is broken, scratched or lacks some screw holes	Feel free to contact us and we will get back to you within 24 hours
	The screw holes on the board and the steel frame don't line up	1. Please tighten the screws on the board by 70%, do not tighten completely 2. Adjust board and steel frame until the screw holes are lined up, then tighten all the screws
	The desk board is uneven or not tight, has gaps after being assembled	1. Loosen the screws in the uneven or gap positions; adjust until the desktops are flat and tight, then tighten the screws 2. If your problem still can't be solved, please feel free to contact us
Steel Frame	The steel frame is bent, broken, painted, rusted or damaged	Feel free to contact us and we will get back to you within 24 hours
	The table is unstable after being assembled	1. Check if the screws are tightened 2. Read through the manual, check if there are any parts installed incorrectly or missing assembly 3. If your problem still can't be solved, please feel free to contact us
	Encountering non-human caused damage during usage	If the product is damaged due to non-human causes, please keep the product and send us photos of it. We will ascertain the cause of the product damage within 48 hours and provide you with a satisfactory solution

Thank you
for choosing our product

Made In China