











*ASSEMBLY INTRODUCTION*





## Exploded View





## Fitting




## Step 1




## Step 2



## Step 3





Bx8




Cx4

## Step 4




Ax4

## Step 5





Bx8





Cx2

## Step 6





Cx10


## Step 7




## Step 8




## Step 9



## Step 10





# Step 11







Bx10

## Step 12





Cx10

## Step 13





Ax6

Step 14



Step 15




Step 16


 Ex8

 Hx4


 Ix4





Step 17






 Ex16




Step 18



Step 19



## Step 20



## Step 21

