




ASSEMBLY INSTRUCTION

MF313154


















Minimum no. 2 of people
recommended to assemble
this product: Approx.
assembly time: 60 mins










PART LIST

1		1PC	2		1PC	3		1PC
4		1PC	5		1PC	6		1PC
7		1PC	8		1PC	9		2PCS
10		1PC	11		1PC	12		1PC
13		3PCS	14		8PCS	15		4PCS
16		1PC	17		4PCS	18		4PCS
19		4PCS	20		4PCS	21		4PCS

HARDWARE LIST


A		18PCS M $\frac{1}{4}$ "X35	B		36PCS M $\frac{1}{4}$ "X25	C		34PCS M $\frac{1}{4}$ "X15	D		44PCS M4x15
E		14PCS M4x30	F		32 PCS M4x15	G		16 PCS 15x20x40H	H		2PCS M3.5x15
i		1PC 174x55x45H	J		8PCS 3x50x50	K		6PCS #20x20x13	L		1PC M4X23X57

STEP 1



A	K
	
M $\frac{1}{4}$ "x35	#20x20x13
4 PCS	4 PCS

STEP 2





A


M $\frac{1}{4}$ "x35
4 PCS



STEP 3

A	C
	
M $\frac{1}{4}$ "x35	M $\frac{1}{4}$ "x15
4 PCS	2 PCS





STEP 4

D

M4x15
8 PCS





STEP 5

D	E
 M4x15	 M4x30
8 PCS	14PCS




STEP 6

C	J
 M4x15	 3x50x50
16 PCS	8 PCS




STEP 7

C
 M $\frac{1}{4}$ "x15
8 PCS







STEP 8

A	C	K
 M $\frac{1}{4}$ "x35	 M $\frac{1}{4}$ "x15	 #20x20x13
6 PCS	8 PCS	2 PCS




STEP 9

H	i
	
M3.5x15	174x55x45H
2 PCS	1 PC




STEP 10

4 SET




G	F
	
15x20x40H	M4x15
16 PCS	32 PCS




STEP 11

4 SET




B

M4x25
36 PCS




STEP 12

4 SET



D

M4x15
28 PCS



STEP 13

