



ASSEMBLY INSTRUCTIONS



























IMPORTANT NOTE:


- ① PLACE ALL PARTS ON A CLEAN AND SMOOTH SURFACE SUCH AS A RUG OR CARPET TO AVOID THE PARTS FROM BEING SCRATCHED.
- ② BEFORE YOU BEGIN, KINDLY FOLLOW THE ASSEMBLY INSTRUCTIONS STEP BY STEP.
- ③ DO NOT TIGHTEN ALL SCREWS AND BOLTS UNTIL THIS ITEM IS FULLY SET-UP.

Detail View



1		2		3		4	
	1pc		1pc		1pc		1pc
5		6		7		8	
	1pc		1pc		1pc		1pc
9		10		11		12	
	1pc		1pc		1pc		1pc
13		14		15		16	
	1pc		1pc		1pc		1pc
18		19		20		21	
	2pcs		2pcs		1pc		2pcs
22		23		24		25	
	1pc		1pc		1pc		2pcs
26		27		28		29	
	2pcs		2pcs		2pcs		1pc
30		31		32		33	
	1pc		2pcs		2pcs		1pc


34		35		36		37	
2pcs		1pc		1pc		1pc	
38							
1pc		Hardware List					

17		39		40		41	
2pcs		1pc		1pc		1pc	
42		43		44			
1pc		1pc		1pc			




Hardware List

A	 Ø 3.5*60 10pcs	B	 Ø 3.5*50 6pcs	C	 Ø 3.5*40 32pcs	D	 Ø 3.5*35 4pcs
E	 Ø 3.0*30 6pcs	F	 Ø 3.0*28 20pcs	G	 Ø 3.0*18 32pcs	H	 Ø 3.0*18 3pcs
I	 Ø 6.0*20 24pcs	J	 Ø 6.0*55 6pcs	K	 Ø 6.0*45 15pcs	L	 Ø 6.0*30 2pcs
M	 Ø 6.0*35 2pcs	N	 2pcs	O	 18pcs	P	 18pcs
Q	 4pcs	R	 3pcs	S	 1pc	T	 5pcs
U	 2pcs	V	 4pcs	W	 1pc		

ASSEMBLY TOOLS REQUIRED(NOT INCLUDED)




PLEASE BE CAREFUL DO NOT DAMAGE THE HOLE POSITION WHEN YOU USE POWERTOOLS !



Step 1

$G*2$	$O*18$	$R*1$


$C*2$



Step 2

$C*2$

$C*2$




Step 3

$C*2$


K*9

Front

A*6



K




Step 4


K*9

Step 5

A*6





C



X2

C*18
I*24
U*2
V*4



C

Step 6



C*18



I*24



U*2



V*4

G*7
R*2

Step 7


G*7	R*2

Step 8

C*2
G*3
J*6


Step 9

C*2	G*3	J*6




Step 10

M*2



Step 11


F*12



Step 12

D*4

L*2



Step 13

A*4

S*1

Step 14

S*1

C*8

Step 15

C*8

B*6



K*6

Step 16

B*6

K*6


P*12



Step 17




P*12



Step 18

F*8




Step 19



F*8


E*6




Step 20




E*6




Step 21




X2






G*12
P*6
Q*4




Step 22




N*2






Attention:
Open by tools,dangerous of getting hurt.

Step 24



Step 25




Step 26




Step 27

H*3
T*5
W*1



Step 28

		
H*3	T*5	W*1



Step 29