

1.First take out all the accessories and put on gloves.
2.Assemble the lamp body with square branches and connecting pipes as shown.
3.Install the hanging plate on the ceiling, and then reserve the main line of the lamp body and the ceiling.Connect the wires, install the ceiling tray and fix it with flower branches.
4.Install the glass on the lamp body, and pay attention to the installation from below to above.

instruction for installation

A		6*100 square branches	4
B		6*200 square branches	4
C		330 Hardware Ring Welding Hook	1
D		160 hardware circle welding hook	1
E		19*200+300 derrick	1
F		120 ceiling disk	1
G		Hanging plate screw	3
H		Hanging board	1
J		The required quantity of glass (frosted) is 30 pieces, and the spare parts quantity is 32 pieces (2 pieces for standby).	