
















































Assembly instruction















Assembly instruction



① x1 	② x1 	③ x1 
④ x1 	⑤ x2 	⑥ x2 
⑦ x1 	⑧ x1 	⑨ x1 
⑩ x1 	⑪ x9 	⑫ x42 
⑬ x2 	⑭ x1 	⑮ x1 
⑯ x1 	⑰ x1 	⑱ x2 
⑲ x4 	⑳ x2 	㉑ x2 
㉒ x1 	㉓ x1 	㉔ x4 

②⑤ x3 	②⑥ x2 	②⑦ x2 
②⑧ x2 	②⑨ x4 	③⑦ x2 
③① x2 	③② x2 	③③ x3 
③④ x1 	③⑤ x2 	③⑥ x2 
③⑦ x1 	③⑧ x1 	③⑨ x1 
④⑦ x1 	④① x1 	④② x1 
④③ x2 	④④ x1 	④⑤ x1 
④⑥ x3 	④⑦ x2 	④⑧ x1 
④⑨ x1 	⑤⑦ x2 	⑤① x3 

Hardware List

A×28 (3+extra)  M8×60mm	B×14(2+extra)  M8×40mm	C×28(3+extra)  M6×60mm
D×8 (1+extra)  M6×48mm	E×62(7+extra)  M6×40mm	F×2(1+extra)  M6×32mm
G×37 (4+extra)  M6×28mm	H×20(3+extra)  M6×15mm	I×4 (1+extra)  M6×15mm
J×4 (1+extra)  M5×57mm	K×4(1+extra)  M5×37mm	L×2 
M-1  M-2  M4	N×2  M3	O×36 (4+extra)  Ø18*Ø8.5*1.5T
P×2  M8×40mm	Q×2  M5×40mm	R×2  M4×12mm
S×2  M4×10mm	T×2(1+extra)  M6×70mm	

1



H×2pcs




M6×15mm

I×2pcs



M6×15mm



2




H×12pcs




M6×15mm


Step1.




Step2.



3




A×2pcs



M8×60mm

G×2pcs




M6×28mm

O×2pcs



Ø18×Ø8.5×1.5T

4



A×2pcs



M8×60mm

G×2pcs





M6×28mm

O×2pcs




Ø18×Ø8.5×1.5T

5




A×4pcs




M8×60mm

C×2pcs



M6×60mm

L×2pcs





O×4pcs




Ø18*Ø8.5*1.5T

6




A×4pcs



M8×60mm

C×2pcs




M6×60mm

O×4pcs



Ø18*Ø8.5*1.5T


7




E×10pcs




M6×40mm





8




B×4pcs



M8×40mm




9




C×2pcs



M6×60mm



10



A×4pcs




M8×60mm


O×4pcs



Ø18×Ø8.5×1.5T




11




C×12pcs



M6×60mm




12




E×2pcs



M6×40mm




13




H×2pcs




M6×15mm





14



S×2pcs




M4×10mm



The part 49 on the left or right side according to your needs

15



B×6pcs




M8×40mm


O×4pcs




Ø18*Ø8.5*1.5T



16




B×4pcs



M8×40mm

F×2pcs



M6×32mm

I×2pcs




M6×15mm


O×4pcs




Ø18*Ø8.5*1.5T



17



A×4pcs




M8×60mm


O×4pcs




Ø18*Ø8.5*1.5T



18



A×8pcs




M8×60mm


O×8pcs




Ø18*Ø8.5*1.5T




19




E×12pcs



M6×40mm




20




E×6pcs




M6×40mm





21




E×4pcs




M6×40mm





22




D×4pcs



M6×48mm





23




G×4pcs



M6×28mm





24





G×12pcs




M6×28mm



25




C×2pcs




M6×60mm

E×4pcs




M6×40mm


26



Step 1.



Step 2.



K×4pcs




M5×37mm

R×2pcs




M4×12mm

27



G×3pcs





M6×28mm

J×4pcs





M5×57mm


28



29



C×4pcs





M6×60mm



H×4pcs




M6×15mm




30




D×4pcs




M6×48mm




31




E×4pcs




M6×40mm



32




E×2pcs




M6×40mm

T×2pcs




M6×70mm



33




C×2pcs




M6×60mm

G×4pcs




M6×28mm




34





E×6pcs




M6×40mm



35



C×2pcs




M6×60mm



G×4pcs




M6×28mm




36




E×4pcs




M6×40mm





37




E×4pcs



M6×40mm





38




G×4pcs



M6×28mm



39




E×4pcs




M6×40mm

G×2pcs





M6×28mm




Tighten all screws 100%

40



41



P×2pcs






M8×40mm

Q×2pcs




M5×40mm


42



43



44



Tighten all screws 100%