










|   |                                                                                   |                |     |
|---|-----------------------------------------------------------------------------------|----------------|-----|
| A |  | M8x45mm        | x8  |
| B |  | M6x45mm        | x16 |
| C |  | M6x35mm        | x8  |
| D |  | M6x10mm        | x2  |
| E |  | M8             | x24 |
| F |  | M6             | x4  |
| G |  | Allen Key M1   | x1  |
| H |  | Allen Key M5   | x1  |
| I |  | Plastic sleeve | x16 |




|                                                                                                                                                                                       |                                                                                                 |                                                                                                  |                                                                                                   |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------|
| 1<br><br>x2                                                                                         | 2<br><br>x2  | 3<br><br>x2  | 4<br><br>x2  |
| 5<br><br>x2                                                                                         | 6<br><br>x2  | 7<br><br>x1  | 8<br><br>x8  |
| 9<br><br><br>x2 | 10<br><br>x2 | 11<br><br>x2 | 12<br><br>x2 |
| 13<br><br>x2                                                                                       | 14<br><br>x2 | 15<br><br>x4  |                                                                                                   |

STEP 1




STEP 2

X2





|   |                                                                                       |     |
|---|---------------------------------------------------------------------------------------|-----|
| C |  | x 2 |
|---|---------------------------------------------------------------------------------------|-----|


Note: please do lock the screw D directly, do not need to tighten it in this step.




### STEP 3




|   |                                                                                     |    |
|---|-------------------------------------------------------------------------------------|----|
| C |  | x4 |
| F |  | x4 |




# STEP 4



# STEP 5



STEP 5



STEP 6

