













PARTS LIST



HARDWARE LIST


NO.	Drawing	Description	Qty	PCS / SET	NO.	Drawing	Description	Qty	PCS / SET
A		⌀15x9	27	PCS	F		⌀3.5x12	14	PCS
B		⌀7x35	27	PCS	G		⌀4x35	8	SET
C		⌀6x30	8	PCS	H			2	PCS
D		⌀3.5x12	26	PCS					
E	E1  E2  E3  E4 	12″	2	SET	I			1	PCS

1 ATTENTION

During assembly, first loosely align all screws with the corresponding pre-drilled holes and then tighten the screws one by one.


STEP 1

B x12pcs
D x12pcs
E1 x2pcs
E2 x2pcs



STEP 2


A x2pcs
B x2pcs



2


STEP 3

A x6pcs
C x3pcs



STEP 4


A x6pcs
C x3pcs



3


STEP 5

A x5pcs
B x5pcs
C x2pcs




STEP 6

F x14pcs




4


STEP 7
A x8pcs
B x8pcs
D x8pcs
E3 x2pcs
E4 x2pcs
G x8pcs
12
A
11
B
10
B
A
13
14
G
G
E4
D
E3
D
D
x2

5

STEP 8

D x6pcs
H x2pcs
I x1pcs



6

STEP 9

