


ASSEMBLY INSTRUCTIONS


ITEM NO.:N707P392140
























IMPORTANT NOTE:

- ① PLACE ALL PARTS ON A CLEAN AND SMOOTH SURFACE SUCH AS A RUG OR CARPET TO AVOID THE PARTS FROM BEING SCRATCHED.
- ② BEFORE YOU BEGIN, KINDLY FOLLOW THE ASSEMBLY INSTRUCTIONS STEP BY STEP.
- ③ DO NOT TIGHTEN ALL SCREWS AND BOLTS UNTIL THIS ITEM IS FULLY SET-UP.

Detail View



N707P392140

1		2		3		4	
1x		1x		1x		1x	
5		6		7		8	
1x		1x		1x		1x	
9		10		11		12	
1x		1x		1x		1x	
13		14		15		16	
1x		1x		1x		1x	
17		18		19		20	
1x		1x		1x		1x	
21		22		23		24	
1x		1x		1x		2x	
25		26		27		28	
2x		1x		1x		1x	
29		30		31		32	
1x		1x		2x		1x	

33		34		35		36	
1x		1x		2x		2x	
37		38		39		40	
1x		1x		2x		2x	
41		42		43		44	
2x		1x		1x		2x	

Hardware List



A	 Ø 3.5*60 16x	B	 Ø 3.5*40 26x	C	 Ø 3.5*35 2x	D	 Ø 3.0*30 6x
E	 Ø 3.0*28 34x	F	 Ø 3.0*18 6x	G	 Ø 3.0*16 20x	H	 Ø 3.0*10 2x
I	 Ø 6.0*20 24x	J	 Ø 6.0*60 4x	K	 Ø 6.0*55 10x	L	 Ø 6.0*45 6x
M	 Ø 6.0*35 2x	N	 Ø 6.0*16 2x	O	 2x	P	 16x
Q	 14x	R	 2x	S	 3x	T	 2x
U	 2x	V	 1x	W	 4x	X	 2x
Y	 4x	Z	 1x	AA	 1x		

ASSEMBLY TOOLS REQUIRED(NOT INCLUDED)



PLEASE BE CAREFUL DO NOT DAMAGE THE HOLE POSITION WHEN YOU USE POWERTOOLS !

P*16




1


P*16

J*4
L*2

A*6



Front





2



		
6.0*60MM	6.0*45MM	AA*1
J*4	L*2	

3


3.5*60MM
A*6




B*18
I*24
X*2
Y*4




4

			
3.5*40MM	6.0*20MM		
B*18	I*24	X*2	Y*4




5



6

		
3.5*60MM	3.5*35MM	AA*1
A*2	C*2	 K*10


M*2



7

6.0*35MM
M*2


E*12



8

3.0*28MM
E*12

A*4
N*2




9

3.5*60MM
A*4

6.0*16MM
N*2

A*4



10

3.5*60MM
A*4

F*6
G*4
R*2
S*2
V*1

S*2	V*1
3.0*18MM	3.0*16MM
F*6	R*2

11

B*8
G*2
S*1

3.5*40MM	3.0*16MM	S*1
B*8	G*2	

12

L*4

6.0*45MM	AA*1
L*4	




13

O*2

O*2

14

Q*14




15



Q*14

16

E*8




17

3.0*28MM

E*8

D*6





18

3.0*30MM

D*6

G*6





19

3.0*16MM

G*6

G*8
U*2




20

3.0*16MM

G*8

U*2

E*6
H*2
T*2



21

3.0*28MM

E*6


3.0*10MM

H*2



T*2

E*8




22

3.0*28MM


E*8

W*4
Z*1



23

~	
W*4	Z*1



24