



Installation & Assembly


PRODUCTION DATE

PACKING CODE



B2  Ant $\varnothing 12/4\text{mm}$ x20	B2  B $\varnothing 12/4\text{mm}$ x20	B2  K $\varnothing 12/4\text{mm}$ x20	V8  L=468mm x1	V25  x4	F1  7x50mm x40	F3  Hex 4mm x1	V41  x1	Z1  x150	U13  L=1100mm x3	B2  CZ $\varnothing 12/4\text{mm}$ x20
A11  ZB0 x4	A9  ZP0 x8	V16  5x16mm x24	E1  8x30mm x32	T1  x8	V19  x2	S1  3,5x16mm x48	V15  x30			

PRODUCTION DATE	PACKING CODE



B	9	3
C	8	6
D	7	3
E	6	1
F	5	1
G	4	2
H	3	2
I	2	3
K	1	2
ID	NUMBER	QUANTITY

V16



5x16mm

E1



x6 8x30mm

x4

V16

1.1

E1

V16



5x16mm

E1



x6 8x30mm

x4

V16

1.2

E1

E1




8x30mm



x12

2


E1

x3


S1  3,5x16mm x2	V19  x2	F1  7x50mm x2	F3  Hex 4mm x8
---	---	---	--



E1  8x30mm x8




F1




7x50mm x12

F3



Hex 4mm



T1




x2







V16










5x16mm

x6







A9



A11

