

















ASSEMBLY INSTRUCTION




ASSEMBLY INSTRUCTION

① 2PCS 	② 2PCS 	③ 2PCS 	④ 2PCS 
⑤ 2PCS 	⑥ 2PCS 		
⑦ 1PC 	⑧ 1PC 		
⑨ 1PC 	⑩ 2PCS 		

ASSEMBLY INSTRUCTION


A	68PCS	B	68PCS	C	2PCS	D	32PCS
							
M6*40		M6*40				φ 3.5*14	
E	8PCS	F	2PCS	G	2PCS	H	2sets
							
M8*30						H1	H2
							
						H3	H4
							φ3.5*20
I	4PCS	J	2PCS	K	2PCS	L	68PCS
							
				M4*18			
M	6PCS						
							

"A" Hardware installation example









Step 1

A 68PCS





M6*40



ASSEMBLY INSTRUCTION

Step 2



X2

B 4PCS




C 2PCS



D 4PCS



Step 3




X2

B 4PCS



Step 4




X2

B 4PCS



Step 5



X2

B 8PCS




ASSEMBLY INSTRUCTION

Step 6

B 4PCS

 Ø15*9.5




X2

Step 7

B 10PCS

 Ø15*9.5
 E 2PCS

 M8*30




Step 8

B 12PCS

 Ø15*9.5
 E 2PCS

 M8*30




Step 9


B 10PCS

 Ø15*9.5
 E 2PCS


 M8*30




Step 10




Step 11



Step 12





Step 13



X2

Step 14

D 16PCS
M3.5*14



OK