






ASSEMBLY INSTRUCTIONS





PLEASE READ ALL THE INSTRUCTION FIRST
BEFORE ASSEMBLING THE PRODUCT.




Part List

				
①x1Pc	②x1Pc	③x2Pcs	④x2Pcs	⑤x1Pc
				
⑥x1Pc	⑦x2Pcs	⑧x1Pc	⑨x1Pc	⑩x4Pcs
				
⑪x4Pcs				

Hardware List


				
M6X35mm	M6X10mm	M6X30mm		
Ax16Pcs	Bx8Pcs	Cx28Pcs	Dx8Pcs	Ex1Pc



PLEASE BE CAREFUL.DO NOT DAMAGE THE HOLE POSITION WHEN YOU USE POWER TOOLS !

Please read the instruction manual carefully before using it.
Please assemble strictly in accordance with the instruction.
Please double check to the ensure that all parts of the package contents intact.
Don't tight all screws until assembly is finished.

Step:1




M6x35mm
Ax4Pcs




Ex1Pc

Step:2




M6x35mm
Ax4Pcs



Ex1Pc

Step:3




M6x35mm
Ax4Pcs




Ex1Pc

Step:4



M6x35mm
Ax4Pcs




Ex1Pc

Step:5




M6x10mm

Bx8Pcs



Ex1Pc



Step:6




M6x30mm

Cx8Pcs



Ex1Pc



Step:7




M6x30mm

Cx8Pcs



Ex1Pc




Step:8





M6x30mm


Cx12Pcs



Ex1Pc



Step:9



Dx8Pcs

