























Assembly Instructions

It is necessary for you to read this instruction first. Pls check the part list and identify every part from this package, in the rare occasion that there will be a wrong part in package, or parts damaged in shipping, or missing some parts, if these cases happened, pls contact us, we will re-send the replacements of parts to you.



PICKLING LIST

A  back wall x1	B  front wall x1	C  side wall x1	D  middle wall x1	
E  side egg cage x1	F  side egg cage x1	G  base of egg cage x1	H  side egg cage x1	
I  x2	J  roof x2	K  top cover for egg cage x1	L  top roof x1	
M  wooden ladder x1	N  side net wall x1	O  top net wall x1	P  top net wall x1	
Q  cage drawer x1	R  front net wall x1	S  back net wall x1	T  support stick x2	U  the track of drawer x2
1  4x40mm x18	2  6x50mm x4	3  3x30mm x20	4  3 x 16mm x30	5  4x50mm x4
6  3x20mm x2	7  Metal handle x1	8  4X10 x1	9  4mm x1	10  x3

Please read whole instructions carefully before assembly, we suggest to assemble on a level surface, two people may be needed for assembly.
Do not screw too hard as it may damage the wood.



C


D



U x2

SCREW 3 :
3x30mm=6pcs


Step1:



A

SCREW 1 :
4x40mm=5pcs


Step2:



B

SCREW 1 :
4x40mm=5pcs

Step3:





E


F



G

SCREW 2:
6x50mm=4pcs

Step4




H



I

SCREW 3:
3x30mm=4pcs

Step5




K

J

SCREW 3:
3x30mm=8pcs

SCREW 4:
3x16mm=4pcs

Step6






L

SCREW 3:

3x30mm=2pcs

Step7



M



R

make sure the iron
mesh towards
the inside



S



SCREW 4:

3x16mm=4pcs

SCREW 5:

4x50mm=4pcs

Step8




N

make sure the iron
mesh towards
the inside

SCREW 1:

4x40mm=4pcs

Step9





P



O




Q

SCREW 1:
4x40mm=4pcs

SCREW 4:
3x16mm=4pcs

Step10



T1



T2



7



10

SCREW 4:
3x16mm=18 pcs

SCREW 6:
3x20mm=2pcs

SCREW 8 : 1pcs

SCREW 9 : 1pcs

Step11

