







Assembly Instructions




PART LIST

①  3PCS	②  4PCS	③  2PCS
④  2PCS	⑤  1PCS	

HARDWARE LIST


A  M6X28 8PCS	B  M6X45 4PCS	C  ϕ5X40 4PCS
D  1PCS	E  ϕ3X12 (2+1)PCS	 4mm 1PCS
 3mm 1PCS		

STEP 1




C X 4PCS

STEP 2



A X 4PCS


STEP 3







B X 4PCS

STEP 4




STEP 5






Note: When connecting the support legs, do not apply excessive force to prevent the screw holes from cracking.

STEP 6



A X 4PCS

STEP 7



	E X 2PCS
	D X 1PCS

STEP 8

