




Installation & Assembly




1 x2




2 x2



3 x2




4 x2




5 x2




6 x2




7 x4



8 x8



9 x2




M6*12

A x8




M6*27


B x32




C x2





- x2




S4 x1






01




02







X2

03




04





B x 16



- x 2

