A X1




F X2



M6X50MM

B X2




G X2



M6X45MM

C X4




H X9



M6X25MM


D X1



E X1




STEP ①




TIGHTEN SCREWS "H" 75% THIS STEP

STEP ②




TIGHTEN SCREWS "H" 75% THIS STEP

STEP ③



TIGHTEN SCREWS "H" 75% THIS STEP

STEP ④



EWS "F" "G" 100% THIS STEP

STEP ⑤

