



K	L 3.5*14								
18PCS	4PCS								
A	B	C 8*40	D 3.5*12	E 3.5*35	F 7*50	G	H	I 4*50	J 8*40
50PCS	50PCS	17PCS	16PCS	22PCS	4PCS	8PCS	2PCS	2PCS	2PCS

1  1350*300 1PS	2  1350*300 1PS	3  1050*285 1PS	4  1050*285 1PS	5  1290*285 1PS
6  1290*285 1PS	7  340*265 4PS	8  340*285 3PS	9  285*60 1PS	10  285*60 1PS
11  1290*60 1PS	12  1350*60 2PS	13  268*60 2PS	14  1320*50 2PS	15  646*398 6PS

Hardware installation demonstration

NOTE:Please make sure "A"hardware tightened and can't be pulled out!

I



II



III



IV

1



	A*26
	C*2

put A on board ①②⑤

put C on board ⑤



	A*10
	C*4

put A on board ③④⑥

put C on board ③④⑥

3



	A*14
	C*11
	D*16
	G*8

put A on board ⑨ ⑩ ⑪ ⑬

put C on board ⑦ ⑧ ⑪

④

Make sure the arrow on the screw align to the hole on the side.

put B on board ⑨⑩⑪



	B*2
	E*8

5

Make sure the arrow on the screw align to the hole on the side.

put B on board ⑪⑬



	B*14

6



	E*12

7



put B on board ⑦⑧

	B*6

8



	B*8

put B on board ⑤⑥

9

Make sure the arrow on the screw align to the hole on the side.

put B on board ⑧



	B*2

⑩



11



	E*2
	F*4

12



put B on board ③④⑦⑧



	B*10

13

put B on board ⑤⑥



	B*8

14





	L*4
	H*2
	I*2
	J*2

15



	K*18



END