







JA25216


ASSEMBLY INSTRUCTIONS





+Spare X 1 A x 5  M8*160mm	+Spare X 1 B x 5  M6*12mm	+Spare X 1 C x 9  Ø7.8*30mm	D x 1  M8*110mm	E x 6  M8*70mm	F x 2  60*20*2mm
+Spare X 1 G x 9  M8	+Spare X 1 H x 9  Ø16mm	+Spare X 1 I x 9  	+Spare X 1 J x 5  Ø9.8*30mm	K x 2  	L x 1  5mm
M x 1  4mm	+Spare X 1 N x 9  Ø50mm				

1



C	x2
Ø7.8*30mm	

D	x1
M8*110mm	


G	x2
M8	

H	x2
Ø16mm	

I	x2

K	x2


2




C	x4
Ø7.8*30mm	

E	x2
M8*70mm	

3





4



J	x4
Ø9.8*30mm	

5



M	x1
	
4mm	


B	x4
	
M6*12mm	

C	x2
	
Ø7.8*30mm	

E	x4
	
M6*70mm	

F	x2
	
60*20*2mm	

6



A	x4
	
M8*160mm	

G	x4
	
M8	

H	x4
	
Ø16mm	

I	x4
	

K	x1
	

L	x1
	
5mm	

N	x8
	
Ø50mm	

7

