
















1.x2 	2.x1 	3.x2 	4.x2 	5.x8 
6.x4 	7.x2 			
A.x1  M4	B.x26  M6x30	C.x26  M6x18	D.x32 	E.x12 
F.x8  M8x30				



1




F.x8




M8x30

2




A.x1




M4

B.x14



M6x30


C.x14



M6x18

Both sides assembled identically


3



A.x1
M4

D.x16


4



A.x1
M4

D.x16

5




A.x1
M4

B.x12
M6x30

C.x12
M6x18

E.x12

6



7

