






















Installation & Assembly





Ax1 	Cx1 	Dx1 	Ex1 	Gx1 
Bx1 			Fx1 	Hx1 
Ix1 	Jx1 	Kx1 	Lx1 	
Mx2 	Nx2 	Ox2 	Px2 	
Qx1 	1) x2 M4  	2) x10  M7x $\frac{70}{2.7}$	3) x2  M6x $\frac{40}{1.5}$	4) x2  M6x $\frac{13}{0.5}$
5) x6  M4x $\frac{15}{0.6}$	6) x64  M4x $\frac{25}{1.0}$	7) x12  M4x $\frac{50}{2.0}$	8) x2 	9) x2 
10) x4  M8x $\frac{20 \times 3}{0.8 \times 0.1}$	11) x4 	12) x2 	13) x10 	14) x2  M6x $\frac{16 \times 1.0}{0.6 \times 0.04}$
1 		2 		
	11) x4 	6) x12 		7) x4 


3



4



5



① x2



M4

② x5



③ x1





④ x1



⑩ x2



6




⑥ x20



⑬ x5




7




6 x4



7 x8




8



6 x8




9



5 x2	9 x2	12 x2	14 x2

10



5 x4	8 x2