


























WCM619HR-010101

①  1PCS	②  1PCS	③  1PCS	④  1PCS
⑤  1PCS	⑥  1PCS	⑦  1PCS	⑧  1PCS
⑨  1PCS	⑩  1PCS	⑪  1PCS	⑫  2PCS
⑬  1PCS	⑭  2PCS	⑮  1PCS	⑯  2PCS
⑰  1PCS	⑱  2PCS	⑲  1PCS	


 A M3.5*45(4PCS)	 B M3.5*40(26PCS)	 C M3.5*30(8PCS)
 D M3.5*25(8PCS)	 E M3.0*23(4PCS)	 F M3.0*18(28PCS)
 G 3PCS		

ASSEMBLY TOOLS REQUIRED(NOT INCLUDED)




PLEASE BE CAREFUL DO NOT DAMAGE THE HOLE
POSITION WHEN YOU USE POWERTOOLS

1



(B) M3.5*40(8PCS)


2



(B) M3.5*40(8PCS)

(E) M3.0*23(4PCS)


3



(A) M3.5*45(2PCS)

(B) M3.5*40(2PCS)


4




(A) M3.5*45(2PCS)

(B) M3.5*40(2PCS)

5




6




(F) M3.0*18(4PCS)

7



Ⓑ M3.5*40(4PCS)


8



Ⓑ M3.5*40(2PCS)


Ⓓ M3.5*25(4PCS)

9




(F) M3.0*18(6PCS)

10




(C) M3.5*30(8PCS)

11




Ⓓ M3.5*25(4PCS)


12



13



(F) M3.0*18(18PCS)



3PCS

14

