


ASSEMBLY INSTRUCTIONS




Notice:

1. Follow the installation instructions. Please confirm all accessories are preset before installation.
2. If you encounter any problems during installation, please contact our customer service.

"SAFETY TIPS:

Static charge may cause dust on foam - clean with a dry or damp cloth.
Small foam strands may be present - handle gently and dispose of properly.
Do not burn or incinerate. Check local recycling guidelines."


Explosion Diagram



If you encounter any problems during installation, please contact our customer service.

Important reminder:





















- △Please sort and check all accessories before assembly.
 - △Please place the product on empty cardboard box or carpet to avoid scratches on it,
 - △Please use proper tools for assembly. Using an electric screwdriver can accelerate the assembly speed, but please do not overtighten the screws.
 - △Please follow the assembly steps and do not skip any of them.
 - △If possible, please find a partner to help you with assembly, which can accelerate assembly.
 - △Keep all small parts of this product away from children. They may cause serious injury.
 - △We hope you can retighten the screws 2 weeks after assembly, and check the tightening procedure of the screws every 3 months.
- If you meet any difficulty, our friendly customer team are always ready to help you.



Warning: Overturning the product can cause serious crushing injuries. We have a wall connection device attached, please use it to hold the furniture following assembly instructions. Do not change the structure of this product in any way. Our products have been tested and meet any all sales specific security measures. We won't be responsible for any modifications, which may cause significant security risks.

If you encounter any problems during installation, please contact our customer service.

HardWare

 Cam Bolt		 Cam Lock		 $\phi 6*30$ Dowel		 M7*38mm Screw	
A	83PCS+2PCS	B	83PCS+2PCS	C	71PCS+2PCS	D	32PCS+2PCS
 M3.5*12mm (white)		 M3.5*12mm		 M5*38mm		 M4*22mm	
E	42PCS+2PCS	F	6PCS	G	8PCS+2PCS	H	8PCS+2PCS
 M5*38mm		 M4*25mm (white)		 M3.5*16mm (white)			
I	2PCS	J	6PCS	K	16PCS+2PCS	L	4PCS
							
M	2PCS	N	85PCS+2PCS	O	16PCS+2PCS	P	2PCS
							
Q	4PCS	R	2PCS	S	2PCS	T	8PCS+2PCS
				 L=12"		 L=12"	
U	1PC	V	8PCS+2PCS	CL	2PCS	CR	2PCS



Tips: The number after "+" represents the spare hardware. please check all hardware on board again.

If you encounter any problems during installation, please contact our customer service.

HardWare

							
L=12"		L=12"					
DL	2PCS	DR	2PCS				




Tips: The number after "+" represents the spare hardware. please check all hardware on board again.

If you encounter any problems during installation, please contact our customer service.

Explosion Diagram of Pack "A1"



PACKED "A1"




If you encounter any problems during installation, please contact our customer service.

PACKED "A1"



1




Ax2



2



Cx1




Dx2


If you encounter any problems during installation, please contact our customer service.

PACKED "A1"




3





Bx2




Cx1



4




Ax4



Ex12



CLx2



CRx2


If you encounter any problems during installation, please contact our customer service.

PACKED "A1"



5



Bx4





Cx2




If you encounter any problems during installation, please contact our customer service.

PACKED "A1"



6




Ax4



7



Cx3





Dx6


If you encounter any problems during installation, please contact our customer service.

PACKED "A1"

8




Cx2



Dx3





Ex2




Mx2




9



Bx4




Cx3




If you encounter any problems during installation, please contact our customer service.

PACKED "A1"



10




Dx1



11





Ax6




If you encounter any problems during installation, please contact our customer service.

PACKED "A1"




12





Bx6



Cx3



13





Dx4

If you encounter any problems during installation, please contact our customer service.


PACKED "A1"

14



Cx4

15





Ex2


If you encounter any problems during installation, please contact our customer service.

PACKED "A1"




16




Ax8




17



Bx4




Cx2




If you encounter any problems during installation, please contact our customer service.

PACKED "A1"


18





Bx4




Cx2



19




Ax10




If you encounter any problems during installation, please contact our customer service.

PACKED "A1"





20



Bx10





Cx6





If you encounter any problems during installation, please contact our customer service.

PACKED "A1"


21








Ax6



Bx6





Cx6



If you encounter any problems during installation, please contact our customer service.



22




If you encounter any problems during installation, please contact our customer service.

PACKED "A1"



23




Ax5



24



Cx4





Dx7


If you encounter any problems during installation, please contact our customer service.

PACKED "A1"



25




Ax5



26



Cx4




Dx7


If you encounter any problems during installation, please contact our customer service.

PACKED "A1"


27




Bx5




Cx4




Dx1




28




Bx5



Cx4





Dx1




If you encounter any problems during installation, please contact our customer service.

PACKED "A1"



29




Ax8



30




Ax5




If you encounter any problems during installation, please contact our customer service.

PACKED "A1"

31




Cx4







32



Bx13




Cx8




If you encounter any problems during installation, please contact our customer service.

33




Ex2



Ux1



Fx4





Sx2

If you encounter any problems during installation, please contact our customer service.

PACKED "A1"


34




Ax12




Fx2




Rx2






35



Bx2




Cx3




If you encounter any problems during installation, please contact our customer service.

PACKED "A1"


36




Bx10




Cx5



A





B




C

37



Jx6





J

If you encounter any problems during installation, please contact our customer service.

PACKED "A1"



38





Gx8

X2

39



Ax8




X2


If you encounter any problems during installation, please contact our customer service.

PACKED "A1"

40




Bx8





X2


41



Ex8



DLx2





DRx2

X2


If you encounter any problems during installation, please contact our customer service.

PACKED "A1"

42




Hx4



Qx2

X2

43




Step A is complete

If you encounter any problems during installation, please contact our customer service.

Explosion Diagram of Pack "B1"



PACKED "B1"




If you encounter any problems during installation, please contact our customer service.

PACKED "B1"


44





0x16




Vx8



45



Kx8





Lx4




Attention: Please tear off the film.

If you encounter any problems during installation, please contact our customer service.


46




Hx4



Ex16






Qx2



If you encounter any problems during installation, please contact our customer service.


47




If you encounter any problems during installation, please contact our customer service.

PACKED "B1"


48




Kx8



Tx8




Nx85




Hardware is included in the stove package

If you encounter any problems during installation, please contact our customer service.


49



Ix2



Px2



Serious of injuries can occur from furniture tipping over. To prevent furniture from tipping over, we recommend that it be permanently fixed to the wall. This product contains wall anchors and hardware. Make sure the hardware fits the wall before installation.

If you encounter any problems during installation, please contact our customer service.