




INSTRUCTION MANUAL







① × 1




② × 1




③ × 1




④ × 1




⑤ × 1




⑥ × 2




⑦ × 1













⑧ × 1














⑨ × 1




⑩ × 1

	
⑪ × 1	⑫ × 1
	
⑬ × 1	⑭ × 3
	
⑮ × 1	⑯ × 2
	
⑰ × 1	⑱ × 1
	
⑲ × 8	⑳ × 2

	
②① × 2	②② × 2
	
②③ × 1	②④ × 1
	
②⑤ × 1	②⑥ × 1
	
②⑦ × 1	②⑧ × 2
	
②⑨ × 1	③⑩ × 1




Hardware List




Ø6×35 mm



Ø15×9 mm



Ø8×30 mm




Ø3.5×14 mm

A x 61


B x 61

C x 51

D x 64




Ø4×40 mm



Ø3×12 mm



M4×18 mm




Ø4×14mm

E x 48


F x 4

G x 5

Hx 2



Ø6×30 mm





I x 1


J x 4

K x 2

L x 2



Ø4×35 mm





M x 10

N x 8

O x 10

P x 1




300 mm

Q x 8

R x 2

Step 1

R	x 2
	
300 mm	





R




R1

R2




R1




R2

Step 2




A	x 28
	

Step 3




A	x 4	R1	x 2	D	x 4
		 300 mm			
					Ø3.5×14 mm

Step 4




B	x 4
 Ø15× 9 mm	

Step 5




B	x 4	A	x 4	C	x 4
					
Ø15× 9 mm					

Step 6




C	x 4	E	x 4
			
		Ø4× 40 mm	


Step 7



Step 8




Step 9



x 2


A	x 8
	

Step 10




C	x 8	B	x 10
		 Ø15× 9 mm	

Step 11




E	x 32
 Ø4× 40 mm	

Step 12




H	x 2
 Ø4× 14 mm	

Step 13




C	x 5	A	x 5	B	x 5	0	x 10
					Ø15× 9 mm		Ø4× 35 mm


Step 14





Step 15



Step 16





Step 17




M	x 10	D	x 10
		Ø3.5x14mm	

Step 18




N	x 8

Step 19




E	x 4
 Ø4×40 mm	

Step 20




A	x 4	B	x 4
		 Ø15× 9 mm	

Step 21




F	x 4	R2	x 2	G	x 1	I	x 1
							
Ø3×12 mm		300 mm		M4×18mm			

Step 22





Step 23



x 2


D	x 16	Q	x 8
 Ø3.5×14 mm			

Step 24








G	x 4	J	x 4	D	x 32
 M4×18mm				 Ø3.5×14 mm	

Step 25



K	x 2	E	x 2
 Ø6×30 mm		 Ø4×40 mm	



Trouble shooting:

