




Diagram illustrating assembly instructions and safety warnings:

- Warning 1:** A warning triangle with an exclamation mark is positioned above a box containing:
 - A circular icon showing an L-shaped metal bracket.
 - An icon of a power drill with a diagonal line through it, indicating that a power drill should not be used.
- Warning 2:** A warning triangle with an exclamation mark is positioned above a box containing:
 - A circular icon showing a rectangular block being placed on a textured surface.
 - An icon of a rectangular block with a diagonal line through it, indicating that the block should not be placed on a soft or uneven surface.
- Time:** A clock icon with the text "40'" below it, indicating an estimated assembly time of 40 minutes.
- Person:** An icon of a person with the text "1" below it, indicating that one person is required for assembly.




F




x 1

G




x 1

H




x 2

I




x 1

J




x 1

K




x 2

L



x 1


M



M4
x
20


x 16

N





x 16

!




1



2

F





x 1

L




x 1





3



E






x 1








4





5




6



D	J	L	M	N
				
x4	x1	x1	x8	x8





7



8



9



!

