




Ax158



M8x $\frac{30}{1.2}$

Bx72



M4x $\frac{30}{1.2}$

Cx12



M6x $\frac{80}{3.2}$

Dx4



M6x $\frac{80}{3.2}$

Ex12



M6x $\frac{70}{2.8}$

Fx12



Gx1



Hx2



M6x $\frac{140}{5.5}$

Ix12



Jx12



Kx1



Lx12




Mx6




M6x $\frac{60}{2.4}$

Ox4











M6x $\frac{120}{4.7}$




mm
inch

x2




① x1 	② x1 	③ x1 	④ x1 		
⑤ x14 	⑥ x14 	⑦ x1 	⑧ x2 		
⑨ x2 	⑩ x2 	⑪ x2 	⑫ x2 		
⑬ x6 	⑭ x2 	⑮ x2 	⑯ x1 	⑰ x22 	⑱ x2 
⑲ x2 	⑳ x2 	㉑ x4 	㉒ x1 		




2

Cx4 	Dx4 	Fx4 	Gx1 	Ix8 	Jx8 
				Lx8 	Ox4 




3


Ax4 	Ex12 	Gx1 
---	---	--




4 x2




5



6



7



Bx4

