




Assembly Instruction (WLF-C23)



Parts List Open the hardware check all parts QTY, thanks



A x 1




B x 1

! Assemble on a mat that is not easy to scratch
The screw must be loose to finish



C x 4



D x 12




E x 4




F x 1

(*D* Screwing tool)
(Tighten clockwise)


Step 1



Step 2



Step 3



Step 4

