


PARTS LIST



HARDWARE LIST


NO.	Drawing	Description	Qty	PCS SET	NO.	Drawing	Description	Qty	PCS SET
A		M6x30	28	PCS	B		4mm	1	PCS
C		M6x25	4	PCS					

1 ATTENTION

During assembly, first loosely align all screws with the corresponding pre-drilled holes and then tighten the screws one by one.

STEP 1


A x16pcs



x 2

STEP 2

A x8pcs




x 2

STEP 3

A x4pcs

C x4pcs



STEP 4

