









A x5
Spec:M6*25




B x5
Spec:M18*8. 2*2



C x4
Spec:38*38




D x2
Spec:Ø3. 5*L32




E x2
Spec:




F x3
Spec:10*4*1




G x1
Spec:Ø4*L16



H x1
Spec:





I x1
Spec:





1

2







3




X=X






5


6






7

8





9
