













115
41
50



A dimension diagram located below the cabinet drawing. It features three arrows originating from a single point. One arrow points vertically upwards and is labeled '115'. Another arrow points horizontally to the right and is labeled '50'. The third arrow points diagonally upwards and to the right, bisecting the angle between the other two, and is labeled '41'.




A34
x8




M116
x4



T83
x16



H1
x8



T7
x8



H2
x10



H54
x18




V5
x28




T98
x8




V38
x8



H14
x2




H15
x4



H139
x4



V32
x8





H16
x1




V98
x2




G128
x8




498x408x12mm



470x373x38mm



1078x388x16mm



1078x388x16mm




492x156x16mm



492x301x16mm



443x350x3mm



1083x478x3mm







350x456x350 H.118 mm








350x456x350 H.200 mm


1




2




3




4




5




6




7



8



9



10

