





mm
inch
x2






Ax2	Bx2	Cx2	Dx2
Ex2	Fx1	①x2	②x4 Size: 4.3x2x0.3cm
③x2 Size: 4.5x1.4x0.3cm	④x2	⑤x4	⑥x18 M6x $\frac{30}{1.2}$
⑦x14 M6x $\frac{20}{0.8}$	⑧x8 M6x $\frac{15}{0.6}$	⑨x16	⑩x2
⑪x1	⑫x2 M6	⑬x32 M6x $\frac{16x1.0}{0.6x0.04}$	⑭x2 M6x $\frac{16x5.0}{0.6x0.2}$
⑮x2 M6x $\frac{16x10}{0.6x0.4}$	⑯x12	⑰x1 M4	

1





⑥ x4 M6x $\frac{30}{1.2}$

⑬ x4 M6x $\frac{16 \times 1.0}{0.6 \times 0.04}$




2





⑥ x4 M6x $\frac{30}{1.2}$


⑬ x4 M6x $\frac{16 \times 1.0}{0.6 \times 0.04}$





3



⑯ x6




4






⑥ x4 M6x $\frac{30}{1.2}$

⑬ x4 M6x $\frac{16 \times 1.0}{0.6 \times 0.04}$






5



⑥ x4 $M6 \times \frac{30}{1.2}$

⑬ x4 $M6 \times \frac{16 \times 1.0}{0.6 \times 0.04}$



6



⑯ x6




7




⑦ x4 $M6 \times \frac{20}{0.8}$

⑬ x4 $M6 \times \frac{16 \times 1.0}{0.6 \times 0.04}$






8




7 x 8



13 x 8



9






8 x 8





5 x 4




9 x 8



10




③ x2





Size: 4.5x1.4x0.3cm


⑨ x4




11




① x2




⑨ x4




12



13



14



15

