



ASSEMBLY INSTRUCTION








A	x1
	
M4	

B	x8
	
M6x12mm	

C	x8
	
M6x28mm	

D	x2
	

1





Screw assembly progress

A	x1
	
M4	

B	x6
	
M6x12mm	

D	x2
	



2



Screw assembly progress

C	x3
	
M6*28mm	

3





Screw assembly progress

B	x2
	
M6x12mm	

C	x1
	
M6x28mm	

4



Please adjust all parts to the optimal position and tighten all screws

C	x4
	
M6*28mm	

