



CP1110I




CP1110I




A x11
Spec: $\phi 15 \times H12$



B x12
Spec: $\phi 8 \times 30$



C x11
Spec: $\phi 7 \times L30$




D x4
Spec: $\phi 6 \times L28$



E x4
Spec: $\phi 12 \times H9$



F x4
Spec: $\phi 3.5 \times L32$




G x4
Spec:




H x6
Spec: $\phi 6 \times L8$




I x1
Spec: 10g
Paste on wood with glue




J x1
Spec: 5#



K x1
Spec: L450



L x8
Spec:



M x8
Spec:



N x8
Spec:




O x8
Spec:



P x15
Spec:





AAA x4
Spec: $\phi 3.8 \times L12$



1


2






3


4




5



6





7

8

