



Assembly Instructions













COMPONENTS ID Nr.

Part Nr.	Qty	Part Nr.	Qty	Part Nr.	Qty
A	1pcs	F	2pcs	L	2pcs
B	1pcs	G	1pcs	M	1pcs
C	1pcs	H	2pcs	N	1pcs
D	1pcs	J	1pcs	P	1pcs
E	2pcs	K	1pcs		




HARDWARE LIST


① x 10  M6x30mm	② x 25  D5x50mm	③ x 1  #4	④ x 1  #3
⑤ x 6 	⑥ x 13  M6x12mm	⑦ x 6 	⑧ x 1 
⑨ x 2  D3.5x15mm	⑩ x 12 	⑪ x 2 	⑫ x 1 
⑬ x 1 			

PRODUCT ASSEMBLY

1



Noted the direction of (M) and (N)




PRODUCT ASSEMBLY

2



D5x50mm



② x 8



Slide opening here




Noted the holes of X support at part (B) are downward here

3


D5x50mm




② x 8



Slide opening here





Noted the holes of X support at part (B) are





PRODUCT ASSEMBLY

4



5



PRODUCT ASSEMBLY

6


M6x30mm



① x 4



⑩ x 4




7

D5x50mm




② x 4



PRODUCT ASSEMBLY


6

D5x50mm
 ② x 5



7

M6x12mm
 ⑥ x 4



PRODUCT ASSEMBLY

8

