

Mounting location for accurate measurements:

Choose a location that is not subject to direct weather elements. An ideal location is out of direct sun, on the North side of a building or in a shady spot.

Optional Calibration:

Compare the thermometer to an existing thermometer with correct readings. Place both thermometers indoors for three hours to adjust to the indoor temperature. If the readings are not the same, turn the calibration knob on back of unit in the appropriate direction to re-calibrate the thermometer. Factory calibration is the recommended setting. This adjustment is optional and only recommended if changes must be made.