



Assembly Instruction









Hammer and Screwdriver
are not included !!

NO.	QTY.	LINEDRAWING
(A)	34	
(B)	34	
(C)	32	 8x40
(D)	24	 3.5x30
(E)	16	 25x6
(F)	16	 3.5x15
(G)	8	
(H)	12	
(I)	8	

Assembly Instruction




1




	A	8x
	D	8x

3




	A	14x
	D	8x

2




	A	8x
	C	6x

4



	B	14x
	C	10x


5



X2



A	B	C	H
6x	6x	4x	6x
			

6




C
8x


7





E
16x


8




D
16x


9



I	F	16x
		8x

10



G	8x
	

