





An icon showing an L-shaped metal bracket inside a circle, and a power drill with a diagonal line through it, indicating that a power drill should not be used for assembly.	A warning triangle icon with an exclamation mark inside.	A clock icon showing the time as approximately 1:50.
An icon showing a rectangular cushion on a textured surface inside a circle, and a screwdriver with a diagonal line through it, indicating that a screwdriver should not be used for assembly.	A warning triangle icon with an exclamation mark inside.	A simple line drawing of a person, representing the number of people required for assembly.
		15'
		1



A	B	C	D
			
x 1	x 2	x 2	x 1




C x 2




B x 2




A







D






E x 4





E	F	G	H
		 M6 x 24	
x 4	x 8	x 8	x 1

1



2



3

