






Assembly instructions for the bed frame, including tool requirements, time, and personnel.


Tools: An icon shows an Allen key and a wrench inside a circle, and a power drill with a diagonal line through it, indicating that a power drill is not required.













Warning: A triangle with an exclamation mark indicates a warning.

Time: A clock icon is shown above the text "30'", indicating the estimated assembly time.







Personnel: An icon of a person is shown above the number "2", indicating that two people are required for assembly.



A	B	C	D	E
				
x 1	x 1	x 2	x 2	x 4









F	G	H	I	J	K
				 M8 x 60	 M8 x 25
x 39	x 4	x 26	x 26	x 4	x 16
L	M	N	O	P	Q
 M8 x 35					
x 8	x 1	x 8	x 12	x 8	x 1



1

A  x 1	B  x 1	G  x 4	J  M8 x 60 x 4	M  x 1	O  x 4
--	--	--	--	--	--












2 x 2

D  x 1	E  x 2	L  M8 x 35 x 4	P  x 4	M  x 1	Q  x 1
--	--	--	---	--	--





3

<p>C</p>  <p>x 2</p>	<p>K</p>  <p>M8 x 25 x 16</p>	<p>M</p>  <p>x 1</p>	<p>N</p>  <p>x 8</p>	<p>O</p>  <p>x 8</p>
---	--	---	---	---



4



5

