














Ax90  M8x $\frac{30}{1.2}$	Bx80  M4x $\frac{30}{1.2}$	Cx12  M6x $\frac{80}{3.2}$	Dx4  M6x $\frac{80}{3.2}$	Ex6  M6x $\frac{70}{2.8}$	
Fx12 	Gx1 	Hx2  M6x $\frac{140}{5.5}$	Ix4 	Jx4 	
Kx1 	Lx4 	Mx6  M6x $\frac{60}{2.4}$	1x1 	2x1 	
3x1 	4x1 	5x8 	6x8 	7x2 	
8x2 	9x2 	10x2 	11x2 	12x2 	
13x6 	14x2 	15x2 	16x1 	17x26 	18x2 
 $\frac{\text{mm}}{\text{inch}}$ x2					


1




2



3




4




Ex6	Gx1

5x2




Ax8	Bx24	Hx2
Ix4	Jx4	Lx4


6



7




8



Bx52



9



Bx4

