



Diagram illustrating assembly steps and safety warnings:

- Step 1:** Shows tools (screwdriver and Allen key) and a power drill. A warning triangle with an exclamation mark is positioned to the right.
- Step 2:** Shows a rectangular block being placed on a surface and another block being secured. A warning triangle with an exclamation mark is positioned to the right.
- Time:** A clock icon indicates a duration of **60'**.
- Personnel:** A person icon indicates that **2** people are required.




1




x 2

2




x 1

3




x 1

4




x 1

5




x 1

6




x 1

7




x 1

8




x 1

9




x 1

10




x 2

11




x 2

12




x 2

13


















x 2



14





x 2

<p>A</p>  <p>M6 x 30</p> <p>x 8</p>	<p>B</p>  <p>M6 x 40</p> <p>x 6</p>	<p>C</p>  <p>x 2</p>	<p>D</p>  <p>M4 x 20</p> <p>x 2</p>
<p>E</p>  <p>x 1</p>	<p>F</p>  <p>x 4</p>	<p>G</p>  <p>x 10</p>	<p>H</p>  <p>x 10</p>
<p>I</p>  <p>M3 x 12</p> <p>x 24</p>	<p>J</p>  <p>x 20</p>	<p>K</p>  <p>M4 x 35</p> <p>x 14</p>	
<p>CL</p>  <p>x 2</p>	<p>CR</p>  <p>x 2</p>	<p>DL</p>  <p>x 2</p>	<p>DR</p>  <p>x 2</p>



1





2






3



4



5






6

H



x6




7

J




x 6




8






9










x 1









9





10







11







12





13






14 x 2



15 x 2



16 x 2






17 x 2

H




x 2




18 x 2




13










x 1



19 x 2



20 x 2




21 x 2

C





x 1


D



x 1



22



23

