




ASSEMBLY INSTRUCTION



① x8
(Bolt M6x15)




② x16
(Bolt M6x60)



③ x8
(Washer 6)



④ x8
(Spring Washer 6)




Ⓐ x2




Ⓑ x2



Ⓒ x2




Ⓓ x2




Ⓔ x2




⑤ x8




⑥ x3




Ⓕ x2



Ⓖ x1



Ⓗ x1



Ⓘ x1

(EXTRA)



① x2
(Bolt M6x15)



② x3
(Bolt M6x60)



③ x2
(Washer 6)




④ x2
(Spring Washer 6)



⑤ x2

ASSEMBLY INSTRUCTION



x2




Step 1

50 %



Step 2


50 %



x1



5

ASSEMBLY INSTRUCTION





x2


Step 3



Step 4




ASSEMBLY INSTRUCTION



x2





Step 5




Step 6

x4

x4







x1

ASSEMBLY INSTRUCTION


Step 7




50 %




Step 8



50 %




ASSEMBLY INSTRUCTION




x1

Step 9



100 %



x4

