Adjustable Height Desk

Assembly Instructions



Please do not load more than 30 lb. when desktop is fully raised.

Adjustable Height Desk Parts List

Please check packaging for all parts and hardware before discarding. Unpack and lay parts on clean, padded surface like carpet or a blanket. Check that you have all parts indicated. Call customer service if any hardware is missing. Before beginning assembly, carefully study the diagrams below and sort your hardware according to the pictures. Using the incorrect hardware will cause damage.

А.		Quantity	В.		Quantity	C.		Quantity
(of 8			of 4			of 2
Bolt	1/4"x1-1/4"L		Bolt	1/4"x1/2"L		Screw	Ф4.0x5/8"L	
D.	0 2222	Quantity of 2	E.	(x))))))))))))))))))))))))))))))))))))	Quantity of 2	F.		Quantity of 4
Anchor			Screw			Adjustable level		
G		Quantity of 1	Η	0	Quantity of 4	I		Quantity of 2
Allen Wrench			Bracket			Plastic Strap		
1 Desk	top	Quantity of 1	2 Side I	Leg Left	Quantity of 1	3 Side Le	eg Right	Quantity of 1
4 Cross	s Bar	Quantity of 1						
Care and Cleaning Instructions: Before using, wipe with a clean, dry cloth. Avoid rubbing or scratching the surface with rough or abrasive objects.								
Assembly Tools Required: No.2 Phillips Screwdriver, Hammer, Power Drill (Not Included)								

Adjustable Height Desk Assembly Instructions









	Parts Replacement Form	
Customer Information		
Name		
Address		
City/State/Zip Code		
Phone Number		
Please indicate where you pur	chased this item: Store/Website/Catalog	
Please indicate color/size/style	e number:	
Style No Parts Let	tter Parts Description	Quantity Needed