




Ax2pcs




Bx2pcs



Step 1



Step 2




Cx8pcs




Dx2pcs




Ex4pcs




Fx2pcs




Step 3




Step 4




Gx2pcs




Hx2pcs




Ix16pcs




Jx4pcs




Step 5




Step 6




Kx2pcs




Lx2pcs



①x16pcs



②x16pcs




③x8pcs



④x16pcs




⑤. 1x3pcs




⑤. 2x3pcs




⑥x36pcs
M6*40mm



⑦x36pcs
M6*22mm



⑧x108pcs
M6*18mm



⑨x1pcs
M5



