













① x 1




② x 1




③ x 1




④ x 1




⑤ x 1




⑥ x 1




⑦ x 1




⑧ x 1




⑨ x 2




⑩ x 1



⑪ x 1




⑫ x 1



⑬ x 2




⑭ x 2




⑮ x 2



⑯ x 1




⑰ x 1



⑱ x 2



19 x 1




20 x 1




21 x 2




22 x 2




23 x 1




24 x 1




25 x 1




26 x 1




27 x 1




28 x 1




29 x 1




30 x 1




31 x 2




32 x 2




33 x 2













34 x 2







35 x 2






36 x 2

					
φ6x35mm A x 64	φ6x60mm B x 2	φ15x9.5mm C x 66	φ6x10mm D x 2	φ6x30mm E x 20	φ6x50mm F x 2
					
M3x14mm G x 19	M3.5x12mm H x 50	M4x14mm I x 30	M4x35mm J x 18	M4x45mm K x 14	L x 2
					 M4x16mm
M x 3	N x 1	O x 1	P x 2	Q x 2	R x 2
					
M4x18mm S x 4	T x 16	U x 2	V x 1	W x 1	DL x 2
					
DR x 2	CL x 2	CR x 2			





Step 1








	
$\phi 6 \times 60 \text{mm}$	$\phi 15 \times 9.5 \text{mm}$
B x 2	C x 2

			
$\phi 6 \times 10 \text{mm}$	$\phi 6 \times 50 \text{mm}$	M3x14mm	
D x 2	F x 2	G x 2	N x 1


Step 2



			
$\phi 6 \times 35 \text{mm}$	M3.5x12mm		
A x 28	H x 8	CL x 2	CR x 2




Step 3




$\phi 15 \times 9.5 \text{ mm}$
C x 2


Step 4




$\phi 15 \times 9.5 \text{ mm}$
C x 4


Step 5




	
$\varnothing 15 \times 9.5 \text{mm}$	$\varnothing 6 \times 30 \text{mm}$
C x 2	E x 2

Step 6




	
$\varnothing 15 \times 9.5 \text{mm}$	$\varnothing 6 \times 30 \text{mm}$
C x 8	E x 2

Step 7




φ15x9.5mm
C x 2

Step 8




φ15x9.5mm
C x 4

Step 9




φ15x9.5mm
C x 6

Step 10




Step 11




	
Ø6x30mm E x 6	M4x45mm K x 6


Step 12





M4x14mm I x 16

Step 13




	
$\phi 6 \times 35 \text{mm}$	$\phi 15 \times 9.5 \text{mm}$
A x 4	C x 4



Step 14





M4x45mm
K x 8


Step 15




		
φ6x35mm A x 6	φ15x9.5mm C x 6	φ6x30mm E x 6

Step 16




			
φ6x35mm	M3x14mm	M3.5x12mm	
A x 18	G x 1	H x 4	
			
L x 2	O x 1	P x 2	M4x18mm
			S x 4

Step 17





$\phi 15 \times 9.5 \text{mm}$
C x 4

Step 18




$\phi 15 \times 9.5 \text{mm}$
C x 10




$\phi 6 \times 30 \text{mm}$
E x 4

Step 19





M4x35mm
J x 10

Step 20



$\phi 15 \times 9.5 \text{ mm}$
C x 4

Step 21




M3.5x12mm
H x 8



V x 1


W x 1

Step 22



M3.5x12mm
H x 4

Step 23




M3.5x12mm
H x 18





M x 3



Step 24




X 2

		
φ6x35mm	φ15x9.5mm	M3.5x12mm
A x 8	C x 8	H x 8
		
M4x35mm		M4x16mm
J x 8	Q x 2	R x 2




	
DL x 2	DR x 2

Step 25



Step 26






M3x14mm
G x 16




T x 16

Step 27



	
M4x14mm I x 8	U x 2

Step 28




M4x14mm I x 6