ASSEMBLY INSTRUCTIONS

PARTS LIST

Z	HARDWARE	Z1 © Ø15 x ø10MM x 9	Z2 Ø22 x ø10MM x 9	Z3 (a) (b) (max 40MM	Z4 (a) (b) (b) (c) (d) (e) (d) (e) (e) (e) (e) (f) (f) (f) (f	Z5 M5 x 100MM x 1
B2	LEG X1			locations. Overtighten bolts will damage the bolt threads. 6 - Use only factory provided hardware to assemble. Unapproved hardware can damage product or jeopardize the structural integrity of the product. 7 - The use of power tool to assemble is not recommended due to high risk of over-torque, which can damage the product.		
B1	LEG X1			 2 - Read this Assembly Instructions from beginning to end before starting to assemble. 3 - Take an inventory of the required parts to ensure all are available. 4 - To prevent accidental choking hazards, keep all packing materials away from small children. 5 - Only tighten hardware until ALL hardware are fully engaged on their 		
A	TABLE TOP			assemble.	position the item on a clear	














ASSEMBLY INSTRUCTIONS

