










Installation & Assembly



PARTS LIST



HARDWARE LIST


NO.	Drawing	Description	Qty	PCS SET	NO.	Drawing	Description	Qty	PCS SET
A		ø 15x9	6	PCS	K		ø 3x12	2	PCS
B		ø 7x35	6	PCS	L		108x25x9MM	2	PCS
C		ø 6x30	6	PCS	M		M4x20	4	SET
D		ø 3. 5x14	2	PCS	N			2	PCS
E			1	SET	O			2	PCS
F		ø 4x40	8	PCS	P		ø 3. 5x16	26	PCS
G		ø 35x190	4	PCS	Q		180x20x3	2	PCS
H		4MM	1	PCS	R			4	PCS
I		M6x20	8	PCS	S		ø 7. 8x38	2	PCS
J			12	PCS					

1 ATTENTION

During assembly, first loosely align all screws with the corresponding pre-drilled holes and then tighten the screws one by one.


STEP 1

B x6pcs
D x2pcs
E₁ x1pc




STEP 2

A x6pcs
C x6pcs
F x6pcs




STEP 3

G x4pcs
H x1pc
I x8pcs



STEP 4

J x12pcs




STEP 5

 E_2 x2pcs

K x2pcs

L x2pcs


M x4pcs



STEP 6


N x2pcs

O x2pcs



STEP 7

P x20pcs




STEP 8

P x6pcs


Q x2pcs

R x4pcs



STEP 9

F x2pcs
S x2pcs



STEP 10

