




















Planting work table




A				1PC	
B				1PC	
C		1PC	D		1PC
E				1PC	

F		1PC	BB	 M6*35 Bolt	8PCS
G		2PCS	CC	 M6*40 Bolt	2PCS
H		1PC	DD	 M6*50 Bolt	4PCS
I		1PC	EE	 M6*45 Bolt	8PCS
J		1PC	FF	 M6*60 Bolt	4PCS
K		1PC	GG	 M4*13 Screw	8PCS
L		2PCS	HH	 M5*40	2PCS
					
M		1PC			
AA		4PCS			


1




2




3






4




5




6




7




8




9




10




11



12



13



14

