


1



x1

2



x1

3



x1

4



M8x20

x2

5



∅ 4.8x13

x2

6



∅ 5x40

x2

7



∅ 20x ∅ 7

x2

8



∅ 8x40

x2

9



∅ 8x40

x2

10



∅ 6x30

x4


11



∅ 3.5x40

x4

12



s=6

x1