












Assembly Instructions




TS CHECKLIST



<p>L</p>  <p>Ax1PC</p>	<p>R</p>  <p>Bx1PC</p>	 <p>Cx2PC</p>	 <p>M6*60 Dx6PCS</p>	 <p>M6*35 Ex4PCS</p>
---	---	--	---	---

 <p>Fx4PCS</p>	 <p>12*6*1.5 Gx6PCS</p>	 <p>Hx1PC</p>
---	--	--






Step 2



Step 3



Step 4